

# Laser Data Collection Project Flare Stack Height Verification

## Project Scope

The request was made to identify the height of a flare stack that was due for replacement of the flare tip. Old construction drawings showed what the elevation should be, but verification was needed.

This information was needed in order to properly plan for the lifting equipment needed for the maintenance project. All information was safely gathered from the ground, near the flare structure.




Figure 1: Final CAD drawing submitted to the client shows the elevations requested in a photographic manner